

# Walpole St Kew Vic 3101

## Residential Basement Waterproofing

### Project Details

This case study describes the careful planning and execution of a pier and beam basement waterproofing job. Despite unexpected challenges and complexities, the team's expertise and determination led to the successful completion of the project.

Location:

Walpole St Kew Vic 3101

Initial Setup:

The installation of a waterproofing system was achieved with precision, using innovative methods to create a dry basement.

Effective Problem-Solving:

Challenges such as a rough cast in the shot creek and puncturing of the membrane system were adeptly handled with the use of liquid rubber and continuous re-coating.

Collaborative Work:

The team worked efficiently with other workers on the site, overcoming coordination difficulties and showing adaptability in a complex working environment.

Persistence and Success:

Despite the builder's liquidation and unexpected hurdles, the team's resilience led to the successful completion of all wall sections, with ongoing plans to finish the under slab.

## Result:

The overall success of the project showcases the team's skill, commitment, and ability to overcome challenges, demonstrating a job well done and a readiness to take on future projects.

Watch [Youtube video](#) about this project.

